

MD 32 Linden Church Interchange

Project Construction Update

November 2012



This picture shows the area that has been excavated for the new bridge abutment (end support) on MD 32 at Linden Church Road.

- Please watch for new traffic patterns.
- Observe new signs and flaggers during lane closures.
- Please drive carefully through the work zone and beyond.
- Watch for construction equipment and working crews.
- Please note: Bicycles are prohibited on MD 32 between Burntwoods Road and MD 108 for the duration of the project. Bicyclists should follow the posted detour route.



This picture shows the start of driving piles for the foundations of the new bridge abutment along the east side MD 32.

Current Progress:

1. Crews have excavated for the new bridge pier (center support) and abutment (end support) on the west side of MD 32 (pictured at top left).
2. Crews have started to drive piles along the east side of MD 32 for the foundation of the bridge abutment (pictured at lower left).
3. Crews have installed erosion and sediment control measures for the first phase of the project. See pictures under the media tab for examples of erosion and sediment controls.

Upcoming Work:

1. Crews will continue installing the remaining erosion and sediment control measures for the first phase of the project.
2. Crews will install barrier wall along MD 32 south of the Linden Church Road intersection.
3. Crews will begin constructing the central pier, or support column, for the new bridge that will carry Linden Church Road over MD 32.
4. Crews will install drainage pipes and relocate utilities.

On behalf of Maryland State Highway Administration, I would like to request your cooperation and patience. Please drive with caution through our work zones.

Brian Pickens

Construction Project Engineer

Maryland State Highway Administration

Project office: 410-531-1723