


## **NOTES:**

- 1. ROUTE MARKER ASSEMBLIES THAT
  REQUIRE SUPPORTS LARGER THAN
  TWO 4" × 4" OR TWO 4" × 6"

  DRILLED WOOD POSTS AND THAT ARE NOT
  PROTECTED BY PHYSICAL TRAFFIC BARRIERS
  SHALL BE INSTALLED ON BREAKAWAY TYPE
  STEEL SUPPORTS.
- 2. REFER TO WOOD SIGN SUPPORTS POSTS SIZES & SPACING STANDARD PLATE FOR DETAILS.

## TYPICAL ROUTE MARKER ASSEMBLY INSTALLATION (48" x 36" SHIELD)



SPECIFICATION CATEGORY CODE ITEMS

812, 813

APPROVED

DIRECTOR - OFFICE OF TRAFFIC AND SAFETY

APPROVAL • SHA
REVISIONS

HIGHWAY ADMINISTRATION

HIGHWAY ADMINISTRATION

## APPROVAL • SHA REVISIONS APPROVAL 2-21-95 REVISED FREVISED REVISED REVISED

## Maryland Department of Transportation STATE HIGHWAY ADMINISTRATION

STANDARDS FOR HIGHWAYS AND INCIDENTAL STRUCTURES

WOOD SIGN SUPPORTS ROUTE MARKER ASSEMBLIES

STANDARD NO. MD 812.03

REFERENCED ON: MD 812.04